

General Information

Date & Time: 14, Jul, 2026 15:57

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	119,784
Registration No.	NHQ2685	Chassis No.	PA1B18F30R4242481
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	103	98	120
2	Boot Lid	111.0	106	103	124
3	Roof	110.5	111	120	102/109
4	Left Front Fender	102.8	106	109	93
5	Left Front Door	109.3	104	111	113
6	Center Panel Left				
7	Left Rear Door	114.0	119	110	113
8	Left Back Panel	120.3	129	111	121
9	Right Front Fender	109.6	110	112	107
10	Right Front Door	108.6	113	107	106
11	Center Panel Right				
12	Right Rear Door	105.0	107	101	107
13	Right Back Panel	105.0	105	104	106

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Medium / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Glove Box - Loose, Deformed - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Small / Trunk Room - Worked - Minimal / Ceiling - Crinkle - Small / Overall Interior - Smell - Yes / Steering Wheel - Worn, Peel, Crack - Small / Room Lamp - Missing - Yes	Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Roof - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Large / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Modified - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes
with LTO plate, with spare tire and key, with jack, no warranty and manual booklet, no reverse camera, no tools, scratches and dent on exterior, scratches in taillight and headlight, issue in headlight bulb.