

General Information

Date & Time: 04, Mar, 2025 08:55

Make	Toyota	Model	Wigo
YOM	2023	Mileage	14,905
Registration No.	NIF3416	Chassis No.	MHKA4DF5FNJ074615
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	112	104	99
2	Boot Lid	101.2	91	105	108
3	Roof	90.5	78	108	85/91
4	Left Front Fender	96.7	100	96	94
5	Left Front Door	94.7	97	99	88
6	Center Panel Left				
7	Left Rear Door	95.7	95	95	97
8	Left Back Panel	93.7	97	95	90
9	Right Front Fender	102.2	105	102	100
10	Right Front Door	97.7	92	103	98
11	Center Panel Right				
12	Right Rear Door	95.2	95	97	94
13	Right Back Panel	94.0	99	91	93

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small	Remarks (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
crack right taillight. dashcam loose. without warranty booklet, spare tire, jack and tools. with LTO plate.