

## General Information

Date & Time: 15, Jul, 2026 07:38

|                  |                   |                   |                   |
|------------------|-------------------|-------------------|-------------------|
| Make             | Toyota            | Model             | Vios              |
| YOM              | 2025              | Odo Meter Reading | 28,643            |
| Registration No. | DCA3240           | Chassis No.       | PA1B18F3XS4290429 |
| CC               | 1.3               | Transmission      | CVT               |
| Fuel Type        | Gas               | Type of Body      | Sedan             |
| Colour           | Blackish Red Mica |                   |                   |

## Body / Panel Condition





| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 127.3         | 108    | 104    | 170      |
| 2  | Boot Lid           | 115.0         | 113    | 107    | 125      |
| 3  | Roof               | 101.3         | 108    | 100    | 98/100   |
| 4  | Left Front Fender  | 102.7         | 106    | 97     | 105      |
| 5  | Left Front Door    | 142.6         | 156    | 109    | 163      |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     | 124.3         | 162    | 101    | 110      |
| 8  | Left Back Panel    | 116.0         | 122    | 119    | 107      |
| 9  | Right Front Fender | 104.5         | 110    | 105    | 99       |
| 10 | Right Front Door   | 109.6         | 113    | 108    | 108      |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    | 106.3         | 108    | 104    | 107      |
| 13 | Right Back Panel   | 102.6         | 104    | 100    | 104      |

## Overall Evaluation :

C

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

| Interior Evaluation : <b>B</b>                                                                                                                                                                                                                                                                                                                           | Exterior Evaluation : <b>E</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>                                                                                                       |  <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| <p><b>Remarks</b><br/>(L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Small / Ceiling - Crinkle - Minimal / Sunvisor, Sunglass Holder - Crinkle - Minimal</p> | <p><b>Remarks</b><br/>(R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch &amp; Dent - Minimal / (L) Rear Door, Molding - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Rear Fender, Molding - Scratch &amp; Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Bumper, Lamps, Panels - Modified - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Modified - Medium / Bonnet, Headlight - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Roof - Scratch &amp; Dent - Small</p> |
| Frame Evaluation : <b>A</b>                                                                                                                                                                                                                                                                                                                              | Functional Evaluation : <b>A</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| <p><b>Remarks</b><br/>Defects not found</p>                                                                                                                                                                                                                                                                                                              | <p><b>Remarks</b><br/>Spare Key - Issue - Unexist</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |

| Inspector Notes                                                                                                                                                                                                  |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| with LTO plate, with spare tire, with reverse camera, no tools and jack, warranty and manual booklet, no spare key, scratches and dent on exterior, scratches on taillight and headlight, taillight crack issue, |