

General Information

Date & Time: 20, Jul, 2026 15:32

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	30,325
Registration No.	DBR1202	Chassis No.	PA1B18F34R4271370
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	114	121	112
2	Boot Lid	123.3	125	116	129
3	Roof	102.2	104	108	95/102
4	Left Front Fender	100.1	98	101	101
5	Left Front Door	103.6	101	104	106
6	Center Panel Left				
7	Left Rear Door	111.6	121	110	104
8	Left Back Panel	110.3	108	115	108
9	Right Front Fender	112.0	118	110	108
10	Right Front Door	156.3	169	148	152
11	Center Panel Right				
12	Right Rear Door	164.3	137	148	208
13	Right Back Panel	257.6	260	221	292

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Cut, Crack - Medium / (R) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Small / Ceiling - Crinkle - Small / (L) Front Floor Mat - Worked - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal	Remarks (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Crack, Gap - Medium / (L) Rear Fender, Molding - Scratch & Dent - Minimal / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet, with jack, no tools, with spare tire, with LTO plate, scratches on tail light, possible flooding, airbag warning lamp on