

General Information

Date & Time: 17, Jul, 2026 17:29

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	25,644
Registration No.	FAT6412	Chassis No.	MHFAA1BY3S0045421
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	102	113	115
2	Boot Lid	91.7	96	95	84
3	Roof	112.3	121	125	106/97
4	Left Front Fender	103.0	102	100	107
5	Left Front Door	121.3	117	117	130
6	Center Panel Left				
7	Left Rear Door	111.0	114	109	110
8	Left Back Panel	107.7	115	111	97
9	Right Front Fender	104.6	105	107	102
10	Right Front Door	98.7	102	98	96
11	Center Panel Right				
12	Right Rear Door	97.0	98	94	99
13	Right Back Panel	99.6	94	98	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small	Remarks (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

no lto plates, no warranty booklet, no spare tire, no jack, incomplete tools, with PMS alarm, with hairline scratches in the body, with stain/paint droplets in the body