

General Information

Date & Time: 14, Jul, 2026 20:27

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	34,618
Registration No.	ZAF6826	Chassis No.	MHKAA1BC6SJ038169
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	127.0	128	125	128
2	Boot Lid	115.0	117	110	118
3	Roof	117.2	116	115	119/119
4	Left Front Fender	108.6	119	103	104
5	Left Front Door	116.3	112	118	119
6	Center Panel Left				
7	Left Rear Door	117.0	122	118	111
8	Left Back Panel	107.0	105	112	104
9	Right Front Fender	100.3	97	103	101
10	Right Front Door	122.6	127	119	122
11	Center Panel Right				
12	Right Rear Door	111.6	106	109	120
13	Right Back Panel	109.0	102	105	120

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Small / Rear Seat - Grime - Medium	Remarks (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

With LTO plate, with warranty booklet, with tools, with jack, no seat cover, with hairline scratches, with spare key 1pc, with spare tire.