

General Information

Date & Time: 14, Jul, 2026 20:11

Make	Toyota	Model	Hilux
YOM	2025	Odo Meter Reading	123
Registration No.	KAU1004	Chassis No.	MR0JB8DD4R3553791
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Gray		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	N / A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain			
Remarks Overall Interior - Smell - Yes / Ceiling - Grime - Large / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Large / Rear Seat - Grime - Large		Remarks Defects not found	
Frame Evaluation :	N / A	Functional Evaluation :	N / A
Remarks Defects not found		Remarks Defects not found	

Inspector Notes
With LTO plate, no warranty booklet, no tools, no jack, no seat cover, no spare key, no spare tire, non-moving vehicle, not starting, worn and flat tires, actual mileage unable to verify due to not starting.