

## General Information

Date & Time: 15, Jul, 2026 15:27

|                  |         |                   |                   |
|------------------|---------|-------------------|-------------------|
| Make             | Toyota  | Model             | Lite Ace          |
| YOM              | 2024    | Odo Meter Reading | 41,438            |
| Registration No. | NFR4957 | Chassis No.       | MHKU3FE10RK006900 |
| CC               | 1.5     | Transmission      | M/T               |
| Fuel Type        | Gas     | Type of Body      | Pickup            |
| Colour           | White   |                   |                   |

## Body / Panel Condition



| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 115.0         | 112    | 112    | 121      |
| 2  | Boot Lid           | 114.3         | 115    | 112    | 116      |
| 3  | Roof               | 114.0         | 112    | 117    | 115/112  |
| 4  | Left Front Fender  | 113.0         | 113    | 113    | 113      |
| 5  | Left Front Door    | 112.0         | 113    | 111    | 112      |
| 6  | Center Panel Left  | 111.6         | 110    | 114    | 111      |
| 7  | Left Rear Door     |               |        |        |          |
| 8  | Left Back Panel    | 112.0         | 111    | 115    | 110      |
| 9  | Right Front Fender | 112.3         | 111    | 111    | 115      |
| 10 | Right Front Door   | 111.3         | 114    | 108    | 112      |
| 11 | Center Panel Right | 113.3         | 113    | 113    | 114      |
| 12 | Right Rear Door    |               |        |        |          |
| 13 | Right Back Panel   | 112.6         | 109    | 116    | 113      |

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

| Interior Evaluation : C                                                                                                                                                                                                                                                                                                                                                       |  | Exterior Evaluation : E                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |  |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>                                                                                                                                                                                                                                                                |  | <p>A : Scratch AU : Scratch &amp; Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust &amp; Corrosion U : Dent X : Defective Y : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |  |
| <b>Remarks</b><br>(L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Small / (R) Front Trim - Worked - Small / (L) Front Trim - Grime - Small / Dashboard - Worked - Minimal / Sunvisor, Sunglass Holder - Worked - Small / Ceiling - Grime - Minimal / (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Worked - Small |  | <b>Remarks</b><br>Cargo Bed Floor - Rust, Corrosion - Medium / Rear Gate - Scratch & Dent - Medium / (R) Side Gate - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small / Front Panel - Scratch & Dent - Minimal / Front Panel - Repair mark - Yes / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Large / (L) Side Gate - Scratch & Dent - Medium |  |
| <b>Frame Evaluation : B</b>                                                                                                                                                                                                                                                                                                                                                   |  | <b>Functional Evaluation : A</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |  |
| <b>Remarks</b><br>Front Floor and Side Member - Traces of Bending, or Marks of Panel Repair ? - Yes                                                                                                                                                                                                                                                                           |  | <b>Remarks</b><br>Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |  |

## Inspector Notes

with LTO plate, with warranty and manual booklet, with inc tools, no jack, no reverse camera, issue on headlight lens, scratches in taillight and headlight, scratches and dent on exterior, no horn issue, rust in cab area.