


General Information

Date & Time: 17, Jul, 2026 16:05

Make	Foton	Model	Traveller
YOM	2020	Odo Meter Reading	142,948
Registration No.	NGN1516	Chassis No.	LVCB2NBA4LS211411
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	335.0	343	329	333
2	Boot Lid	122.3	105	130	132
3	Roof	352.2	664	231	227/287
4	Left Front Fender	295.3	343	194	349
5	Left Front Door	377.0	430	458	243
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	433.3	1,080	103	117
9	Right Front Fender	203.0	232	232	145
10	Right Front Door	206.0	207	234	177
11	Center Panel Right	183.6	142	223	186
12	Right Rear Door	220.3	208	215	238
13	Right Back Panel	205.6	116	246	255

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Inspector Notes
overheating issue/ plate light issue/ check engine light on/ power window issue/ possible flooding/ horn issue/ radio issue/ head light and tail light issue/ no jack and tools/ no warranty booklet/ with LTO plate/