

General Information

Date & Time: 17, Jul, 2026 16:16

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	25,723
Registration No.	CCG6488	Chassis No.	PA1B18F31R4274954
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.2	115	98	109
2	Boot Lid	95.6	95	98	94
3	Roof	92.4	89	91	85/105
4	Left Front Fender	95.8	98	98	92
5	Left Front Door	99.8	96	97	106
6	Center Panel Left				
7	Left Rear Door	101.7	107	97	101
8	Left Back Panel	99.1	102	100	95
9	Right Front Fender	97.7	95	101	98
10	Right Front Door	99.2	97	89	112
11	Center Panel Right				
12	Right Rear Door	98.0	88	97	109
13	Right Back Panel	104.6	108	104	102

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small	Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Door, Molding - Dent - Small / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no spare tire/ light scratches around the exterior/ with jack and spare tire/ with LTO plate and warranty booklet/