

General Information

Date & Time: 20, Jul, 2026 15:46

Make	Toyota	Model	Veloz
YOM	2025	Odo Meter Reading	18,233
Registration No.	NJC2441	Chassis No.	MHFAB1BY1S3134447
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Pearl White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	109	109	113
2	Boot Lid	127.6	132	114	137
3	Roof	130.5	152	135	118/117
4	Left Front Fender	120.0	115	117	128
5	Left Front Door	133.6	126	131	144
6	Center Panel Left				
7	Left Rear Door	133.0	136	121	142
8	Left Back Panel	141.6	153	131	141
9	Right Front Fender	123.6	133	122	116
10	Right Front Door	138.3	137	144	134
11	Center Panel Right				
12	Right Rear Door	131.3	153	115	126
13	Right Back Panel	146.3	151	138	150

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal	Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / Roof - Dent - Small / Bonnet, Headlight - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, with warranty and manual booklet, with reverse camera, with spare tire, with jack and inc tools, no spare key, scratches and dent on exterior, scratches in taillight and headlight.