

General Information

Date & Time: 20, Jul, 2026 15:11

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	11,306
Registration No.	CDA8283	Chassis No.	PA1B18F38S4306000
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.3	122	112	124
2	Boot Lid	122.6	122	120	126
3	Roof	111.2	119	100	113/113
4	Left Front Fender	102.0	105	101	100
5	Left Front Door	105.3	108	105	103
6	Center Panel Left				
7	Left Rear Door	104.6	107	101	106
8	Left Back Panel	114.3	113	117	113
9	Right Front Fender	108.0	102	110	112
10	Right Front Door	109.6	105	105	119
11	Center Panel Right				
12	Right Rear Door	110.0	104	104	122
13	Right Back Panel	108.0	109	101	114

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
no tools and spare tire/ light scratches around the exterior/ with jack and LTO plate/ with warranty booklet