

General Information

Date & Time: 23, Jul, 2026 15:29

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	141,452
Registration No.	NIN5414	Chassis No.	PA1B18F39P4207807
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	110	104	112
2	Boot Lid	254.3	198	200	365
3	Roof	48.6	0	0	106/89
4	Left Front Fender	103.6	97	100	114
5	Left Front Door	106.3	100	103	116
6	Center Panel Left				
7	Left Rear Door	118.0	122	119	113
8	Left Back Panel	163.0	158	149	182
9	Right Front Fender	240.6	463	130	129
10	Right Front Door	94.4	96	94	93
11	Center Panel Right				
12	Right Rear Door	101.2	92	97	115
13	Right Back Panel	134.6	138	127	139

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Worn as per age - Yes / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small / Mat Other - Worked - Small / Rear Seat - Worn - Yes	Remarks (R) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Rear Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / Member (Bolted) - Dent - Yes / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Crack, Gap - Medium / Roof - Scratch - Small / Trunk Hood, Rear Gate - Crack, Gap - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on tail light, repair marks on rear side of rear fender,