

General Information

Date & Time: 17, Jul, 2026 16:06

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	69,560
Registration No.	NKO5263	Chassis No.	MHFAA1BY1S0040721
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	117	114	107
2	Boot Lid	113.0	111	112	116
3	Roof	117.5	108	126	118/118
4	Left Front Fender	109.3	117	109	102
5	Left Front Door	125.6	138	115	124
6	Center Panel Left				
7	Left Rear Door	122.6	134	118	116
8	Left Back Panel	121.3	120	124	120
9	Right Front Fender	105.3	106	108	102
10	Right Front Door	118.3	125	117	113
11	Center Panel Right				
12	Right Rear Door	115.6	110	125	112
13	Right Back Panel	104.6	100	105	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	Remarks Bonnet, Headlight - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Large / (R) Mirror - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch & Dent - Small / (R) Front Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
light scratches around the exterior/ no jack and tools/ possible flooding/with spare tire and warranty booklet/ with LTO plate/