

General Information

Date & Time: 04, Mar, 2025 09:14

Make	Toyota	Model	Wigo
YOM	2023	Mileage	36,890
Registration No.	BAC8032	Chassis No.	MHKA4DF5FNJ072476
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.3	99	100	99
2	Boot Lid	102.0	95	110	101
3	Roof	80.1	74	87	79/80
4	Left Front Fender	94.3	90	99	94
5	Left Front Door	82.2	81	83	83
6	Center Panel Left				
7	Left Rear Door	86.1	93	85	80
8	Left Back Panel	90.7	98	91	83
9	Right Front Fender	88.3	90	90	85
10	Right Front Door	89.7	87	94	89
11	Center Panel Right				
12	Right Rear Door	88.0	90	87	87
13	Right Back Panel	93.7	98	90	93

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large / Rear Seat - Grime - Small	Remarks (R) Front Fender - Repair Traces - Yes / (R) Rear Door, Molding - Scratch - Small / (R) Rear Door, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / (L) Front Fender, Molding - Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Roof Spoiler, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ no spare tire and tools/ with jack and LTO plate/