

General Information

Date & Time: 17, Jul, 2026 16:11

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	10,004
Registration No.	BAH3633	Chassis No.	MHKAA1BC8SJ039419
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.6	128	131	133
2	Boot Lid	114.0	112	124	106
3	Roof	106.7	111	106	108/102
4	Left Front Fender	104.0	109	100	103
5	Left Front Door	113.6	111	117	113
6	Center Panel Left				
7	Left Rear Door	258.0	150	476	148
8	Left Back Panel	104.3	102	107	104
9	Right Front Fender	96.5	96	102	92
10	Right Front Door	115.3	115	112	119
11	Center Panel Right				
12	Right Rear Door	119.0	116	120	121
13	Right Back Panel	105.6	102	111	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Glove Box - Loose, Deformed - Large / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	Remarks (L) Rear Door - Repair Traces - Yes / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Power Steering - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
traction control light on/ airbag warning light on/ power steering issue and warning light on/ air-conditioning issue/ power window issue/ head light issue/ tail light issue/ radio issue/ horn issue/ turn signal issue/ no tools and jack/ no warranty booklet/ light scratches around the exterior/ with spare tire and LTO plate