

General Information

Date & Time: 17, Jul, 2026 16:09

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	34,573
Registration No.	CCD6674	Chassis No.	PA1B18F37S4289223
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.3	131	117	128
2	Boot Lid	118.6	118	108	130
3	Roof	110.7	111	113	107/112
4	Left Front Fender	108.6	106	109	111
5	Left Front Door	105.0	107	98	110
6	Center Panel Left				
7	Left Rear Door	112.3	120	108	109
8	Left Back Panel	117.3	120	121	111
9	Right Front Fender	106.0	108	107	103
10	Right Front Door	107.5	114	109	100
11	Center Panel Right				
12	Right Rear Door	117.6	115	115	123
13	Right Back Panel	125.0	120	122	133

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Mat Other - Grime - Medium / (R) Front Trim - Grime - Medium / (R) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Small / Carpet - Worked - Minimal	Remarks (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With Lto plate, with spare tire and jack, with warranty booklet and tools, 2keys, scratches on headlights and taillights, worn rear tires,