

General Information

Date & Time: 20, Jul, 2026 14:36

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	11,632
Registration No.	CCD9676	Chassis No.	PAHAD9DA0S1627929
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	111	114	113
2	Boot Lid	104.4	118	107	88
3	Roof	115.7	114	111	121/117
4	Left Front Fender	117.3	114	123	115
5	Left Front Door	102.0	104	98	104
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	70.9	56	82	75
9	Right Front Fender	122.6	126	133	109
10	Right Front Door	108.0	101	106	117
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	85.1	73	98	85

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal / Carpet - Worked - Minimal / (L) Front Floor Mat - Worked - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal / Rear Gate - Scratch - Small / Cargo Bed Floor - Scratch - Medium / (L) Side Gate - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with spare tire, 1key, no warranty booklet and tools and Jack, scratches on headlights,possible flooding