

General Information

Date & Time: 20, Jul, 2026 15:07

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	22,075
Registration No.	NJK6190	Chassis No.	PAHACACA2S6429183
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	109	108	100
2	Boot Lid	52.7	56	49	54
3	Roof	118.2	123	122	115/113
4	Left Front Fender	107.3	105	107	110
5	Left Front Door	106.6	105	108	107
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	61.4	64	59	62
9	Right Front Fender	104.6	105	110	99
10	Right Front Door	98.2	106	110	79
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	70.6	71	76	66

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Large / (L) Guard Frame - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Cargo Bed Floor - Scratch & Dent - Large / Rear Gate - Scratch & Dent - Small / (R) Guard Frame - Scratch & Dent - Large / (R) Side Gate - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / Roof - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Horn - Issue - Yes

Inspector Notes
no jack and tools/ light scratches around the exterior/ horn issue/ with LTO plate and warranty booklet/ with spare tire